Firehouse, Engine Company No. 6 (Independent Fire Company) 416 Gay Street
Baltimore
Baltimore County
Maryland

HABS MD, 4-BALT,

HABS No. MD-353

WRITTEN HISTORICAL AND DESCRIPTIVE DATA
REDUCED COPIES OF MEASURED DRAWINGS

Historic American Buildings Survey National Park Service Department of the Interior Washington, D.C. 20240 Form 10-920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

MD, 4-BALT, 168-

DATE

3/27/84

## ARCHITECTURAL DATA FORM

				168-	
STATE Maryland .			TOWN OR VICINIT Baltimore	TOWN OR VICINITY Baltimore	
HISTORIC NAME OF STRUCTURE (INC Firehouse, Engine Compar		NAME)		HABS NO. MD-353	
SECONDARY OR COMMON NAMES OF (Independent Fire Compar	_				
COMPLETE ADORESS (DESCRIBE LOCA	ATION FOR RURAL	SITES)			
416 Gay Street					
OATE OF CONSTRUCTION (INCLUDE SOURCE) 1853 (Clarence Forrest, Our Firemen, p. 49) Reason and Wetherall					
SIGNIFICANCE (ARCHITECTURAL ANI	D HISTORICAL, INC	LUDE ORIGINAL USE	OF STRUCTURE)	<u></u>	
A Baltimore landmark, or firehouses of the city.	ne of the few s	urviving ninetee	nth century vol	unteer	
STYLE (IF APPROPRIATE)	Revival				
MATERIAL OF CONSTRUCTION (INCLI 8rick bearing walls with	UDE STRUCTURAL				
Two story main block with 5 story floor plans see HA8S meast exterior Features of NOTE The bond painted brown from the ctrim; a small wooden cupola was story to the small wooden cupola was small wooden.	story tower; 17 sured drawings main block of ground to the f with a molded s	'x89'x44'; wedge and field record the building is o irst floor window heet metal cornic	-shaped. s. of red brick laws ws and buff abo ce; a hose towe	aid in a running ove with brown er on the roof	
of the northwest corner of the INTERIOR FEATURES OF NOTE (DESC) Four brass poles which lead for supported by cast iron column the engine; a small iron circle.	RIBE FLOOR PLANS from the second as arranged in	floor bunk room pairs from the so	to first floor outhwest and no	; second floor	
MAJOR ALTERATIONS AND ACCITION 1874 Rusticated reinfor 1885 Quarters extended 1904 Building cleaned a	cement at the by purchase of		\$6500)		
PRESENT CONDITION AND USE Fai firehouse in 1964.	rly poor condi	tion when resear	ched in 1964; s	till used as	
	e of Membership imore); colore	for Robert G. Fo d lithograph show and engine house	wing firehouse		
Forrest, Clarence H. Our Fire Baltimore Together w and Wilkens, 1898	emen,Official H	istory of the Fi	re Department o	of the City of	

COMPILER, AFFILIATION Eleni Silverman Historian, HABS from reports by John Waite, N.P.S. Architect (Aug. 1964)

## EXTERIOR FEATURES OF NOTE (CONT'D):

is crowned with machicolations and parapet. The first level of the tower is concrete laid on cast iron which has been scored to simulate dressed stone. The other levels are of brick painted buff with stone, cast iron and sheet metal trim.

The opening for the engine is spanned by an arch, now filled from the spring line with imitation rusticated work in stucco, on which is imposed a large quatrefoil bearing the number 6. The doors are modern.

The second story contains a pair of trefoil arched openings on three sides. The third and fourth stories are similar in design: on each face is a pair of openings separated by a narrow brick pier. Each of the openings is set within a rectangular brick frame. The trefoil arch springs from engaged cast iron colonettes with plain inverted-bell capitals. The fifth story has two floors: a belfry and clock tower. On each face of the belfry is a triple opening similar in detail to the openings below. Around the opening is a blank semicircular arch formed by pilaster strips.